



Alenia Module Aug. '99




Can see
dicing
non-uniformity

Alenia Module Aug. '99




More pressure
near center of
module

Alenia Module Aug. '99



Same die as previous slide but edge of module. Less pressure.

Alenia Module Aug. '99



Only region
that may have
merged bumps

Notice also
dicing difference